

Midpeninsula Regional Open Space District - Specifications For The Remediation of Asbestos and Lead from the Exterior of the Mt. Um Radar Tower and Cleanup of Chipped Debris from Ground Cover
Appendix A

Barracades - Paint Chips From Baricade, not Tower



Bench Adjacent To Tower - with Paint Chips



Bench Wiht Paint Chips



Damage Wall - Tower



Damaged Paitn At Sealed Door to Tower



Fall Protection For Lift



Fall Protection For Roof



HMS-M17224-01A AGC and Paint



HMS-M17224-01PB Metal




HMS-M17224-02A AGC and Paint (same locations as



HMS-M17224-02PB



HMS-M17224-03A Paint Chips On Bench



HMS-M17224-04A Deteriorating
AGC and Paint



HMS-M17224-05A 2nd Story
Coatings



HMS-M17224-06A Above AGC
3rd Story



HMS-M17224-07A 3rd Story
Coating at Column



HMS-M17224-21 Penetration
Sealant Cementitious



HMS-M17224-22A Roof
Penetration Mastic - East Edge



HMS-M17224-23A Roof
Penetration Mastic - North Edge



HMS-M17224-24A Paint on
Brackets and Stands



HMS-M17224-25A Roofing and
Mastic at Gear Device



HMS-M17224-26A Mastic Under
Single Ply



HMS-M17224-27A Mastic on
Pad By Gear Device



HMS-M17224-28A Flashing
Mastic



HMS-M17224-29A Single Ply Roofing



HMS-M17224-100A Blue Paint on Wood



HMS-M17224-101A Beige Plaster with Green Paint



HMS-M17224-102A Green-Biege Paint on Wood



HMS-M17224-103A Brown Coating On Wood



HMS-M17224-104A Plaster From Pool Area



HMS-M17224-104A Pool Area Plaster



HMS-M17224-105A Beige Floor Tile (1960s)



HMS-M17224-106A Green Tile on Wood



HMS-M17224-108A White Paint On Wood



HMS-M17224-110A White Floor Tile (1960s)



HMS-M17224-111A Plain Wood Floor Tile



HMS-M17224-112A Cloth Debris



HMS-M17224-114A Mastic on Winch



HMS-M17224-116A Wallboard or Tile



Ceramic Tile and Grout Old Pool Area



HMS-M17224-117A Ceramic Tile and Grout



HMS-M17224-118A Brown Paint On Wood



HMS-M17224-119A Large Plastic Chunk



HMS-M17224-120A Floor Tile



HMS-M17224-121A Unknown Deris



HMS-M17224-122A Multi-Layered Plaster



HMS-M17224-123A Canvas with Coating



Lader - with LBP



LEAD - HMS-M17224-01PB
Chunk of Metal




LEAD - HMS-M17224-03PB
White Paint on Wood



LEAD - HMS-M17224-04PB
Ceramic Tile Glaze



Lead Roof Jack - Tower Roof



Old Pool Area



Peeling AGC and Paint



Peeling Paint - Tower Roof



Peeling Paint - Tower Walls



Peeling Paint And Anti Graffiti
Coating - Tower Walls 2



Peeling Paint And Anti Graffiti
Coating - Tower Walls 3




Peeling Paint And Anti Graffiti
Coating - Tower Walls 4



Peeling Paint And Anti Graffiti
Coating - Tower Walls 5



Peeling Paint And Anti Graffiti Coating - Tower Walls



Peeling Paint at Entry Ceiling



Pile of Debris Collected by MROSD Staff



Radar Tower North Face



Serpentine Rock Boulder - Outside Tower



Serpentine Rock Boulder Outside of Tower 2



Walkway East Of Tower



Winch Stored In Contractor Staging Area (assumed LBP)

